MEASURING
ELECTRONIC HYGRO-THERM

Electronic precision instrument for measuring the temperature, humidity and the highest and lowest values of both (MAX-MIN function).

Limits	Temperature from -10°C to +60°C
	Humidity from 10% to 99% R.H.
Max. error	± 1°C within -10°C to + 55°C
	± 5% R.H. within 25% to 75% R.H. and 0°C to 50°C
Battery	LR44 or AG13

USE:

1. Open the battery compartment by pushing the cover on the back of the instrument downwards as indicated by the arrow. Remove the battery safety strip and the protection foil on the display. The instrument is now ready for use.
2. The left display now shows the current temperature in °C. The right display shows the relative humidity in %.
3. Displaying maximum/minimum values.
   a. Pressing the MAX/MUM button, the highest values since the unit was last re-set appear.
   b. Pressing the same button again gets you the lowest values since the unit was last re-set.
   a. To return to the current values, press the MAX/MIN button again.
4. Resetting the MAX/MIN memory to the present values
   Press the CLEAR button.

Source of error: Please change the battery before making any complaint. Maltreating or unauthorised tampering with the unit invalidates the guarantee!